



# Cosmic Helm Bracelet

By Charity Dorn

## Materials:

30 - 18g swg 11/32

24 - 18g swg 1/4

11 - 18g swg 5/32

1 - 14mm Cosmic Ring

Clasp

(Ring count above is for a 7.5" bracelet)

Pictures in tutorial use bright aluminum, but due to the looseness of this design any metal will work.

Start by closing 20 of the 18g 1/4 rings and 1 of the 18g 11/32 rings (you can set this closed 18g 11/32 ring off to the side next to your 14mm cosmic ring). Sort the 20 closed 18g 1/4 rings into two piles of 10. This is just to help keep track of where you are. One pile will be for the first half of the bracelet and the other for the second half of the bracelet. Set one pile aside for now.

Open a new 18g 11/32 ring and scoop up 4 of the closed 18g 1/4 rings. Close that ring.



Now double that ring by adding a second 18g 11/32 through the same 4 closed 18g 1/4 rings and closing that ring.



Open a new 18g 11/32 ring and pass it between the two closed 18g 11/32 rings in your weave, but around the two 18g 1/4 rings. Close that ring.



Open an 18g 11/32 ring, scoop up two closed 18g 1/4 rings and then pass it through the two 18g 1/4 rings your just put a ring around in the last step. Make sure the new ring does not pass through the last 18g 11/32 ring, but stays on top. Close that ring.



Open an 18g 11/32 ring and pass it through the two 18g 1/4 rings at the end of your weave.



Now roll the whole weave towards you and pass the open ring you are holding through the 18g 1/4 rings from the other side of the last closed 18g 11/32, again making sure to not go through that ring but keep the new ring on top. Close that ring.



Open another 18g 11/32 ring and pass it between the two closed 18g 11/32 rings in your weave, but around the two 18g 1/4 rings. Close that ring.



Continue that pattern until you are out of closed 18g 1/4 rings in your first pile and you have added two 18g 11/32 rings without the pre-closed 18g 1/4 rings on them.



Open one of the remaining four 18g 1/4 rings that you didn't close at the beginning. Scoop up the single 18g 11/32 ring you closed, pass it through the end two 18g 11/32 rings then add the 14mm cosmic ring (make sure it's face up) and close the ring.



Double that ring by adding a second 18g 1/4 ring right next to the first. Close that ring.



Open an 18g 11/32 ring and pass it between the cosmic ring and the 18g 11/32 behind it. Close that ring. First half done!



Open one of the remaining 18g 1/4 rings and pass it through the cosmic ring and the 18g 11/32 ring behind it. Close that ring. Double it by adding the last remaining 18g 1/4 ring next to it. Close that ring.



Open an 18g 11/32 ring and pass it between the cosmic ring and the 18g 11/32 ring behind it. Close that ring.



Open another 18g 11/32 ring and scoop up two closed 18g 1/4 rings from your second pile and pass it through the two 18g 1/4 rings you just put a ring around in the last step. Make sure the new ring does not pass through the last 18g 11/32 ring, but stays on top. Close that ring.



You are now back to the basic helm weave used for the first half of the bracelet. Finish the weave until you have used all the closed 18g 1/4 rings (ending with the 18g 1/4 rings at the end).



Open an 18g 5/32 ring and scoop up the clasp and attach it to the end 18g 1/4 rings at the end of your bracelet making sure the clasp is facing the correct way for the crystal to be showing on top of your bracelet.



Next we're going to make a small mobius for the end of the extender chain. This isn't necessary, but it's a nice finish to an extender.

Close one 18g 5/32 ring. Open another 18g 5/32 ring and pass it through the first. Close that ring.



Open another 18g 5/32 ring and pass it through the center of both rings you just closed. Close that ring.



Make sure your rings are all laying in the same spiraling direction.



Use the remaining 18g 5/32 to make a 1 by 1 chain and connect the mobius to the other end of your bracelet.



Finished!

